

# CARBIDE INSTRUCTIONS

## THANK YOU

Thank you for the opportunity to work with you. Please follow the instructions below to ensure that your materials are properly insured and received.


- **Maximum weight:** 50 lbs. Please do not exceed this limit when placing materials in the crate.

Additionally, kindly write your quote number below:

QUOTE # .....


### STEP 1

Please place all carbide or other rare earth materials into the provided bags while they are still inside the box.



### STEP 2

Use the green zip tie to close the top of the bag and tuck the corners of the bag into the crate.



### STEP 3

Place the white paper back into the crate, make sure you write your Quote #, Close the Crate use the two black zip ties to close the box, and lock it closed. You can trim the zip ties once they have been attached.



### STEP 4

Use the (3) three provided pieces of tape to tape the box closed.



### STEP 5

Take the pre-paid/pre-printed label out and attach the label to the box securely.



### STEP 6

Drop off the box at the UPS store and keep your tracking number for reference.

